



46 Brampton Road
Eastbourne
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KM66KFT

BMW 1 Series 120d xDrive Sport 5dr [Nav] Step Auto

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
4

Details

Reg. date	17/10/2016	VIN	WBA1T120905E46584	CAP Average	£3,100.00
Year	2016	Body Style	Hatchback	CAP Below	£2,575.00
Mileage	148,042 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	08/10/2025	Gears	8
Colour	BLACK	CAP Clean	£3,625.00	Doors	5

£100 ADDITIONAL FEE.


Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 2 UpTo 10mm

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Dented
2 Or Less UpTo 10mm



9: Door nsr
Chipped
1 To 5



10: Qtr Panel nsr
Dented
Over 30mm



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%



13: Boot Lid
Rusted
UpTo 5mm



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osr
Scratched
Over 50mm




16: Door osr
Chipped
Edge Chip



17: Door osr
Dented
Over 2 UpTo 10mm



18: Door osf
Dented
Between 10mm + 30mm



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK