



46 Brampton Road  
Eastbourne  
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

YC19LBN

## Inspection

Serious Damage? No

## Vehicle

VAT Margin

V5 Present

nama  
GRADE  
4

## Details

Reg. date 30/06/2019

Year 2019

Mileage 48,618 Miles  
Warranted

Fuel Type Petrol

Colour BLACK

VIN YV1MZ32T0K2178789

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 4

Last service date 25/09/2024

Last service miles 37,377

MOT Due 30/06/2026

CAP Clean £10,700.00

CAP Average £9,600.00

CAP Below £8,550.00

Gearbox AUTOMATIC

Gears 6

Doors 5

Last service 25/09/2024 at 37377 miles (4 main dealer services)

## Tyres

NSF MAXXIS 6.0mm

NSR BUDGET OK

OSF MAXXIS 6.0mm

OSR FALKEN 5.0mm

Spare

## Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsr  
Scratched  
UpTo 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint





9: Qtr Panel osr  
Chipped  
Multiple Chips



10: Wheel osr  
Scratched  
Over 50mm



11: Door osr  
Scratched  
Over 25mm Thru Paint



12: Door osf  
Dented  
Between 10mm + 30mm



13: Wing osf  
Scratched  
Over 25mm Thru Paint



14: Wheel osf  
Scratched  
Up To 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK