



VEHICLE INSPECTION REPORT

SD68KKJ

Renault Captur 0.9 TCE 90 GT Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	29/09/2018	Keys	2	CAP Clean	£5,950.00
Year	2018	Service history	Yes	CAP Average	£5,125.00
Mileage	61,373 Miles Warranted	Service documents	Service Book	CAP Below	£4,325.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLACK/CREAM	Last service date	10/02/2022	Gears	5
VIN	VF1R8700961255353	Last service miles	20,248	Doors	5
Body Style	Hatchback	MOT Due	12/02/2026		

Last service 10/02/2022 at 20248 miles. (2 services (1 main dealer). Book & print. Abs light is on

Tyres

NSF	NANKANG	6.0mm
NSR	CONTINENTAL	5.0mm
OSF	NANKANG	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel osf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Dented
Between 10mm + 30mm



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Scratched
UpTo 25mm Thru Paint



12: Door osf
Dented
Between 10mm + 30mm



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK