



# VEHICLE INSPECTION REPORT

**GU66LXT**

## Honda Civic 1.4 i-VTEC SE Plus 5dr [Nav]

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
4

### Details

Reg. date 21/10/2016

Year 2016

Mileage 70,383 Miles  
Warranted

Fuel Type Petrol

Colour BLUE

VIN SHHFK1760GU002366

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 9

Last service date 13/05/2025

Last service miles 68,910

MOT Due 16/11/2025

CAP Clean £5,850.00

CAP Average £5,075.00

CAP Below £4,275.00

Gearbox MANUAL

Gears 6

Doors 5

Last service 13/05/2025 at 68910 miles (9 services (5 main dealer)).

### Tyres

NSF BUDGET 5.0mm

NSR BUDGET 5.0mm

OSF BUDGET 5.0mm

OSR BUDGET 5.0mm


Spare

## Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door Moulding nsf  
Scratched (Painted)  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Door Moulding nsr  
Scratched (Painted)  
Over 25mm Thru Paint





9: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint



12: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Door osr  
Dented  
With Paint Damage





15: Door osf  
Dented  
Over 30mm



16: Screen Front  
Chipped  
Over 10mm



17: Wheel osf  
Scratched  
Over 50mm



18: Roof  
Chipped  
1 To 5

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**                      Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK