



# VEHICLE INSPECTION REPORT

**GY65BTZ**

## Hyundai I20 1.4 Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	14/10/2015	Keys	2	CAP Clean	£6,925.00
Year	2015	Service history	Yes	CAP Average	£6,000.00
Mileage	14,856 Miles Warranted	Service documents	Service Book	CAP Below	£5,075.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	MANUAL
Colour	GREY	Last service date	18/09/2024	Gears	6
VIN	NLHB351CLFZ032612	Last service miles	13,462	Doors	5
Body Style	Hatchback	MOT Due	13/10/2025		

Last service 18/09/2024 at 13462 miles (9 main dealer services). ABS and traction control light on

### Tyres


NSF	FALKEN	4.0mm
NSR	FALKEN	4.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos






## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
Over 100mm Thru Paint



2: Boot Lid  
Scratched  
Over 25mm Not Thru Paint





3: Qtr Panel osr  
Dented  
With Paint Damage



4: Wheel osr  
Scratched  
Over 50mm




5: Door osr  
Dented  
Over 2 UpTo 10mm



6: Door osr  
Scratched  
Over 25mm Not Thru Paint



7: Door osf  
Chipped  
1 To 5



8: Door osf  
Scratched  
Over 25mm Not Thru Paint



9: Wing osf  
Chipped  
1 To 5




10: Wheel osf  
Scratched  
Over 50mm



11: Bumper Front  
Scratched  
25 to 100mm Thru Paint



12: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



13: Bonnet  
Chipped  
1 To 5



14: Wheel nsf  
Scratched  
Over 50mm






15: Wing nsf  
Scratched  
Over 25mm Thru Paint



16: Door nsf  
Chipped  
1 To 5



17: Door nsf  
Scratched  
UpTo 25mm Not Thru Paint



18: Door nsr  
Chipped  
1 To 5



19: Door nsr  
Scratched  
Over 25mm Not Thru Paint



20: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



21: Wheel nsr  
Scratched  
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK