



VEHICLE INSPECTION REPORT

LY05XAB

Mercedes-Benz CLK CLK350 ELEGANCE

| Inspection | | Vehicle | |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | TBC |



Details

| | | | | | |
|-----------|------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 29/07/2005 | VIN | WDB2093562F173224 | CAP Average | £710.00 |
| Year | 2005 | Body Style | Coupe | CAP Below | £400.00 |
| Mileage | 98,332 Miles Warranted | Keys | 2 | Gearbox | AUTOMATIC |
| Fuel Type | Petrol | MOT Due | 26/10/2025 | Gears | 7 |
| Colour | SILVER | CAP Clean | £1,125.00 | | |

Brake wear light on and srs fault

Tyres

| | | |
|-------|---------|-------|
| NSF | DAVANTI | 4.0mm |
| NSR | MAXXIS | 4.0mm |
| OSF | DAVANTI | 4.0mm |
| OSR | BUDGET | 4.0mm |
| Spare | | |

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear armrest
- ABS
- Central locking
- Front parking sensor
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- Drivers airbag
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Front electric windows
- Rear headrests
- Isofix child seat anchor points
- Leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
UpTo 3mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
Over 100mm Thru Paint




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint




8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Poor Previous Repair
Poor Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osf
Dented
Over 30mm



15: Wing of
Dented
With Paint Damage



16: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|-------|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | Fault | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |