



## VEHICLE INSPECTION REPORT

**LX06YML**

### Vauxhall Corsa 1.2i 16V Design [80] 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
5

#### Details

Reg. date 03/03/2006

Year 2006

Mileage 102,876 Miles  
Warranted

Fuel Type Petrol

Colour SILVER

VIN W0L0XCF6864167514

Body Style Hatchback

Keys 2

Service history Yes

Service documents Printout

Number of stamps 9

Last service date 23/02/2017

Last service miles 66,151

MOT Due 07/03/2026

CAP Clean £200.00

CAP Average £200.00

CAP Below £200.00

Gearbox MANUAL

Gears 5

Doors 5

£65 ADDITIONAL FEE LAST SERVICE 23/2/17 @ 66151 MILES (9 SERVICES) PRINT Steering feels notchy and suspension knocking

#### Tyres

NSF CONTINENTAL 4.0mm


NSR BUDGET Worn

OSF LAUFENN Illegal

OSR BUDGET Worn


Spare

#### Photos






## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Poor Paint



2: Bumper Front  
Cracked  
Over 25mm






3: Headlamp os  
Broken  
Replace



4: Other  
N/A  
N/A



5: Wing nsf  
Poor Previous Repair  
Poor Paint



6: Screen Front  
Chipped  
UpTo 10mm



7: Door nsf  
Chipped  
1 To 5



8: Sill ns  
Rusted  
Over 5mm



9: Door nsr  
Chipped  
Multiple Chips



10: Qtr Panel nsr  
Chipped  
1 To 5



11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



12: Bumper Rear  
Poor Previous Repair  
Paint Flake



13: Boot Lid  
Chipped  
1 To 5



14: D Post os  
Poor Previous Repair  
Poor Paint





15: D Post ns  
Poor Previous Repair  
Poor Paint




16: Qtr Panel osr  
Chipped  
1 To 5



17: Door osr  
Dented  
Over 30mm



18: Door osf  
Chipped  
1 To 5



19: Door osf  
Scratched  
Over 25mm Not Thru Paint



20: A Post os  
Poor Previous Repair  
Poor Paint



21: Wing osf  
Chipped  
1 To 5



22: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



23: A Post ns  
Poor Previous Repair  
Poor Paint



24: Door Pad osf  
Broken  
Replace



25: Door Pad nsf  
Torn  
Over 10mm



26: Door Pad nsr  
Torn  
Over 10mm





27: Door Pad osr  
Torn  
Over 10mm




28: Other  
N/A  
N/A




29: Tyre nsr  
Worn  
Replace



30: Tyre osr  
Worn  
Replace



31: Tyre nsr  
Worn  
Replace



32: Tyre osr  
Worn  
Replace

**Interior**



**Carpet Condition**  
**Seat Condition**

Average  
Poor

**Upholstery Condition**  
**Odour**

Poor  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK