



# VEHICLE INSPECTION REPORT

**DL60ORO**

## Vauxhall Meriva 1.4T 16V [140] Exclusiv 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	10/02/2011	Keys	1	CAP Clean	£620.00
Year	2011	Service history	Yes	CAP Average	£260.00
Mileage	90,110 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	SILVER	Last service date	26/11/2020	Gears	6
VIN	W0LSD9EE7B4055254	Last service miles	58,080		
Body Style	MPV	MOT Due	10/11/2025		

£50 ADDITIONAL FEE. Last Service: 26/11/2020 at 58080 miles. (6 services (1 main dealer) ). Book & print.

### Tyres

NSF	GOODYEAR	2.0mm
NSR	GOODYEAR	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Steel wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Other  
N/A  
N/A




2: Bumper Front  
Poor Previous Repair  
Poor Paint






3: Bonnet  
Chipped  
1 To 5



4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint




5: Door nsf  
Dented  
With Paint Damage



6: Sill ns  
Dented  
Over 30mm



7: Sill ns  
Dented  
2 Or Less UpTo 10mm




8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Boot Lid  
Dented  
Over 2 UpTo 10mm



11: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



12: Qtr Panel osr  
Dented  
With Paint Damage



13: Door osr  
Dented  
With Paint Damage



14: Door osf  
Poor Previous Repair  
Poor Paint



15: Wing osf  
Dented  
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK