

VEHICLE INSPECTION REPORT

VE60FVZ

Renault Scenic 1.6 VVT Dynamique TomTom 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	28/01/2011	Keys	2	CAP Clean	£620.00
Year	2011	Service history	Yes	CAP Average	£240.00
Mileage	117,964 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	MANUAL
Colour	BLACK	Last service date	24/05/2012	Gears	6
VIN	VF1JZ1U0644352582	Last service miles	18,010		
Body Style	MPV	MOT Due	13/03/2026		

£50 ADDITIONAL FEE LAST SERVICE 24/5/12 @ 18010 MILES (1 MAIN DEALER) BOOK INPUT ERROR OF MILEAGE IN 2016

Tyres

NSF	YOKOHAMA	4.0mm
NSR	YOKOHAMA	5.0mm
OSF	YOKOHAMA	4.0mm
OSR	YOKOHAMA	4.0mm
Spare		

Features


- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Poor Previous Repair
Poor Paint



2: Boot Lid
Poor Previous Repair
Poor Paint



3: Qtr Panel osr
Dented
With Paint Damage



4: Wheel osr
Scratched
Up To 50mm




5: Door osr
Dented
Over 30mm



6: Door osf
Poor Previous Repair
Poor Paint



7: Wing osf
Chipped
1 To 5




8: Wing osf
Scratched
Over 25mm Not Thru Paint



9: Wheel osf
Scratched
Over 50mm



10: Screen Front
Chipped
UpTo 10mm



11: Roof
Scratched
Over 25mm Not Thru Paint



12: Bonnet
Chipped
Multiple Chips



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Wheel nsf
Scratched
Over 50mm



15: Wing nsf
Chipped
1 To 5




16: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



17: Door nsf
Scratched
Over 25mm Thru Paint



18: Door nsr
Chipped
1 To 5



19: Door nsr
Scratched
Over 25mm Not Thru Paint



20: Wheel nsr
Scratched
Over 50mm



21: Qtr Panel nsr
Dented
With Paint Damage



22: C Post ns
Dented
Over 30mm



23: Roof
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK