

# VEHICLE INSPECTION REPORT

**BJ62FPV**

## Hyundai I10 1.2 Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	01/11/2012	VIN	MALAN51CLDM242056	CAP Average	£1,350.00
Year	2012	Body Style	Hatchback	CAP Below	£950.00
Mileage	58,315 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	19/01/2026	Gears	5
Colour	SILVER	CAP Clean	£1,750.00	Doors	5

£100 ADITONAL FEE  
NO SERVICE HISTORY

### Tyres

NSF	BUDGET	Punctured
NSR	RAPID	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	Worn
Spare		

## Features


- PAS
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Central locking
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint






3: Wing nsf  
Chipped  
1 To 5



4: Door nsf  
Dented  
Over 2 UpTo 10mm



5: Door nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsr  
Chipped  
1 To 5




7: Qtr Panel nsr  
Dented  
With Paint Damage




8: Wheel nsr  
Scratched  
Over 50mm



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



11: Qtr Panel osr  
Dented  
Over 30mm



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Chipped  
1 To 5



14: Door osr  
Scratched  
Over 25mm Not Thru Paint





15: Door osf  
Chipped  
1 To 5




16: Wing osf  
Chipped  
1 To 5




17: Screen Front  
Chipped  
UpTo 10mm



18: Wheel osf  
Scratched  
Over 50mm



19: Tyre nsf  
Punctured  
Replace



20: Tyre osr  
Worn  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK