



# VEHICLE INSPECTION REPORT

**BD64VYC**

## Peugeot 5008 1.6 HDi Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	10/11/2014	Body Style	MPV	MOT Due	02/10/2025
Year	2014	Keys	1	CAP Clean	£2,475.00
Mileage	82,300 Miles Warranted	Service history	Yes	CAP Average	£2,025.00
Fuel Type	Diesel	Number of stamps	2	CAP Below	£1,575.00
Colour	WHITE	Last service date	27/09/2024	Gearbox	MANUAL
VIN	VF30E9HD8ES087501	Last service miles	76,122	Gears	6

£65 ADDITIONAL FEE SERVICES CONFIRMED BY KAP AUTO PANELS LTD Last service 27/09/2024 @ 76122 miles (2 MAIN DEALER SERVICES) Car judders on idle  
Release bearing noisy  
Engine slightly knocking  
Intermittent starter motor fault

### Tyres


NSF	BUDGET	2.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


- Cruise control
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels
- Front parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear parking sensor
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
Over 100mm Thru Paint



2: Bumper Front Grill  
Broken  
Replace





3: Bonnet  
Chipped  
1 To 5



4: Wheel osf  
Scratched  
Up To 50mm



5: Wing osf  
Chipped  
1 To 5



6: Door osf  
Chipped  
1 To 5



7: Door osr  
Dented  
2 Or Less UpTo 10mm



8: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



9: Wheel osr  
Scratched  
Over 50mm




10: Bumper Rear  
Poor Previous Repair  
Rippled UpTo 30%



11: Boot Lid  
Dented  
Over 30mm



12: Qtr Panel nsr  
Chipped  
1 To 5



13: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



14: Wheel nsr  
Scratched  
Over 50mm





15: Door nsr  
Dented  
Over 30mm



16: Door nsf  
Dented  
Over 2 UpTo 10mm



17: Door nsf  
Scratched  
Over 25mm Not Thru Paint



18: Wheel nsf  
Scratched  
Over 50mm



19: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



20: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK