



VEHICLE INSPECTION REPORT

YT12PCZ

Nissan Qashqai 2.0 N-Tec 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/03/2012	Keys	3	CAP Clean	£2,275.00
Year	2012	Service history	Yes	CAP Average	£1,825.00
Mileage	106,088 Miles Warranted	Service documents	Service Book	CAP Below	£1,375.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	CVT
Colour	BLACK	Last service date	09/09/2024	Gears	1
VIN	SJNFBAJ10U2506854	Last service miles	99,464	Doors	5
Body Style	Hatchback	MOT Due	08/09/2025		

Last Service - 09.09.2024 at 99464 miles (12 services) Slight exhaust leak and noise from gearbox

Tyres


NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	4.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Alloy wheels
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- Central locking
- PAS
- Radio/CD
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- Remote central locking

Photos





Condition Check




Damage Photos



1: Other
N/A
N/A



2: Other
N/A
N/A



3: Bonnet
Dented
With Paint Damage



4: Bumper Front
Poor Previous Repair
Poor Paint



5: Wheel nsf
Scratched
Over 50mm




6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint




10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm




16: Door osr
Dented
With Paint Damage



17: Door osf
Dented
With Paint Damage



18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



19: Wing osf
Scratched
Over 25mm Not Thru Paint



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		