



VEHICLE INSPECTION REPORT

GY63XNN

Peugeot 2008 1.6 e-HDi Allure 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 23/01/2014

Year 2014

Mileage 62,944 Miles
Warranted

Fuel Type Diesel

Colour BLUE

VIN VF3CU9HP0DY089540

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 10

Last service date 20/05/2025

Last service miles 60,944

MOT Due 23/11/2025

CAP Clean £2,450.00

CAP Average £1,975.00

CAP Below £1,550.00

Gearbox MANUAL

Gears 5

Doors 5

£100 ADDITIONAL FEE. Last service 20/05/2025 at 60,944 miles, 10 services (3 MAIN DEALER SERVICES)

Tyres

NSF GOODYEAR 3.0mm

NSR BUDGET 3.0mm

OSF GOODYEAR 5.0mm

OSR GOODYEAR 3.0mm


Spare

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Rear
Poor Previous Repair
Poor Paint



2: Boot Lid
Chipped
1 To 5

No Image



3: Boot Lid
Scratched
Over 25mm Not Thru Paint

4: Wheel osr
Scratched
Over 50mm



5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



6: Door osr
Chipped
1 To 5



7: Door osf
Chipped
1 To 5

No Image

8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Door Mirror Assy osf
Broken
Replace



10: Wheel osf
Scratched
Over 50mm



11: Wing osf
Chipped
Multiple Chips



12: Bonnet
Chipped
Over 5mm



13: Bumper Front
Poor Previous Repair
Poor Paint



14: Wheel nsf
Scratched
Over 50mm



15: Wing nsf
Poor Previous Repair
Poor Paint



16: Door nsf
Poor Previous Repair
Poor Paint



17: Door nsr
Chipped
1 To 5



18: Door nsr
Scratched
Over 25mm Not Thru Paint



19: Wheel nsr
Scratched
Over 50mm



20: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image

21: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK