

VEHICLE INSPECTION REPORT

YF58KZD

BMW X5 3.0sd M Sport 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	12/12/2008	VIN	WBAFF02060L290391	CAP Average	£2,675.00
Year	2008	Body Style	Estate	CAP Below	£2,150.00
Mileage	111,154 Miles Warranted	Keys	1	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	19/02/2026	Gears	6
Colour	BLACK	CAP Clean	£3,200.00		

Tyres

NSF	CONTINENTAL	3.0mm
NSR	DUNLOP	3.0mm
OSF	CONTINENTAL	2.0mm
OSR	DUNLOP	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5

No Image

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Poor Previous Repair
Poor Paint



8: Door nsr
Chipped
1 To 5

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Chipped
1 To 5

No Image



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Bumper Reflector nsr
Broken
Replace



16: Lamp nsr
Broken
Replace




17: Boot Lid
Dented
With Paint Damage



18: Qtr Panel nsr
Dented
With Paint Damage



19: Qtr Panel osr
Chipped
1 To 5



20: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




21: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



22: Wheel osr
Scratched
Over 50mm



23: Door osr
Chipped
1 To 5



24: Door osr
Scratched
Over 25mm Not Thru Paint



25: Door osf
Chipped
1 To 5



26: Door osf
Scratched
Over 25mm Not Thru Paint



27: Wing osf
Chipped
1 To 5

28: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK