

VEHICLE INSPECTION REPORT

WV57PKA

Volkswagen Golf 2.0T GTI 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		by 5
		V5	TBC		
Details					
Reg. date	25/09/2007	VIN	WVWZZZ1KZ8W074329	CAP Average	£1,550.00
Year	2007	Body Style	Hatchback	CAP Below	£1,150.00
Mileage	138,787 Miles	Keys	2	Gearbox	MANUAL
	Warranted	MOT Due	Expired	Gears	6
Fuel Type	Petrol	CAP Clean	£1,975.00	Doors	5
Colour	BLACK		·		

£100 ADDITIONAL FEE. Eml on and exhaust blowing

_		
ı	v	res

NSF	NEXEN	3.0mm	
NSR	BUDGET	3.0mm	
OSF	BUDGET	2.0mm	
OSR	BUDGET	2.0mm	
Spare			

Features

- Electric door mirrorsFront electric windowsRear headrests

- Drivers airbagTraction controlAlloy wheels

- Rear wiper

- Air conditioning
 Front head restraints
 Metallic Paint
 Isofix child seat anchor points
 Central locking
- Radio/CD

- Climate control
 Height adjustable drivers seat
 3x3 point rear seat belts
 Passenger airbag
 Remote central locking

- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

Photos













Eastbourne Car Auctions










Condition Check



Damage Photos



1: Roof Lining Torn Over 3mm




2: Seat Back Cover osf Torn Over 3mm



3: Bonnet Chipped Multiple Chips



4: Bumper Front Scratched Over 100mm Thru Paint



5: Wing nsf Rusted Over 5mm



6: Wheel nsf Scratched Over 50mm



7: Door nsf Dented With Paint Damage



8: Door nsr Dented Over 30mm



9: Qtr Panel nsr Dented With Paint Damage



10: Wheel nsrScratchedOver 50mm



11: Bumper Rear Poor Previous Repair Poor Paint



12: Boot Lid Dented Over 2 UpTo 10mm



13: Qtr Panel osr Rusted Over 5mm



14: Wheel osr Scratched Over 50mm



15: Door osr Poor Previous Repair Paint Flake



16: Door osf Dented Over 30mm



17: Screen Front Chipped UpTo 10mm



18: Wing osf Rusted Over 5mm



19: Wheel osf Scratched Over 50mm

Interior

Carpet Condition
Seat Condition

Average Poor **Upholstery Condition Odour**

Poor No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK