



VEHICLE INSPECTION REPORT

PX61UJS

Nissan Qashqai 1.5 dCi [110] N-Tec 5dr

Cat: N

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
5

Details

Reg. date	01/09/2011	VIN	SJNFCAJ10U2351107	CAP Average	£830.00
Year	2011	Body Style	Hatchback	CAP Below	£425.00
Mileage	106,127 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	18/09/2025	Gears	6
Colour	GREY	CAP Clean	£1,225.00	Doors	5

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair. Smoking and eml on
Boot doesn't open due to switch missing
Oil leak

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	Illegal
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Broken
Replace




8: Door nsf
Dented
With Paint Damage



9: Door nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Dented
With Paint Damage



14: Other
N/A
N/A



15: Wheel osr
Scratched
Over 50mm



16: Qtr Panel osr
Chipped
1 To 5



17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Door osr
Dented
With Paint Damage



19: Door osf
Dented
With Paint Damage



20: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Wing osf
Chipped
1 To 5



23: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		