



VEHICLE INSPECTION REPORT

HN07XET

Nissan Pathfinder 2.5 dCi Aventura 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	30/05/2007	VIN	VSKJVWR51U0202447	CAP Average	£830.00
Year	2007	Body Style	Estate	CAP Below	£425.00
Mileage	146,622 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	30/10/2025	Gears	6
Colour	BLACK	CAP Clean	£1,250.00		



£65 ADDITIONAL FEE. Traction control and esp light on

Tyres		
NSF	BUDGET	2.0mm
NSR	BUDGET	4.0mm
OSF	RAPID	6.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
With Paint Damage



6: Screen Front
Chipped
UpTo 10mm



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Dented
With Paint Damage



9: Door nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Rusted
UpTo 5mm



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osr
Scratched
Over 50mm




16: Qtr Panel osr
Dented
With Paint Damage



17: Sill os
Rusted
Over 5mm



18: Door osf
Chipped
1 To 5




19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



21: Wing osf
Chipped
1 To 5



22: Wing osf
Scratched
Over 25mm Not Thru Paint



23: Wheel osf
Scratched
Over 50mm



24: Handle Inner osf
Damaged
Replace



25: Roof
Rusted
Over 5mm



26: Handle Outer nsf
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Poor
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK