



# VEHICLE INSPECTION REPORT

**HV11UPY**

## BMW 3 Series 318i ES 4dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama  
GRADE  
**4**

### Details

Reg. date	25/03/2011	VIN	WBAPF52050A786599	CAP Average	£690.00
Year	2011	Body Style	Saloon	CAP Below	£350.00
Mileage	94,258 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	24/09/2025	Gears	6
Colour	SILVER	CAP Clean	£1,075.00	Doors	4

£100 ADDITIONAL FEE. Gearbox fault while selecting reverse

### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Over 5mm



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wheel nsf  
Scratched  
Over 50mm




4: Wing nsf  
Poor Previous Repair  
Poor Paint



5: Door nsf  
Poor Previous Repair  
Poor Paint



6: Door nsr  
Dented  
Between 10mm + 30mm




7: Door nsr  
Scratched  
Over 25mm Not Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Bumper Rear  
Poor Previous Repair  
Poor Paint



12: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




13: Qtr Panel osr  
Dented  
With Paint Damage



14: Wheel osr  
Scratched  
Over 50mm



15: Door osr  
Scratched  
UpTo 25mm Thru Paint



16: Door osr  
Scratched  
Over 25mm Not Thru Paint



17: Door osf  
Dented  
With Paint Damage



18: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



19: Roof  
Chipped  
1 To 5



20: Wing osf  
Poor Previous Repair  
Poor Paint





21: Wheel osf  
Scratched  
Over 50mm

22: Other  
N/A  
N/A

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK