

VEHICLE INSPECTION REPORT

AU15NNZ

Renault Scenic 1.6 dCi Limited Energy 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		gwa5
		V5	TBC	-	
Details					
Reg. date	01/03/2015	VIN	VF1JZ120D52284676	CAP Average	£1,750.00
Year	2015	Body Style	MPV	CAP Below	£1,300.00
Mileage	78,018 Miles Warranted	Keys	2	Gearbox	MANUAL
		MOT Due	05/01/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£2,200.00		
Colour	SILVER		<u> </u>	-	
Tyres					
NSF		RAPID		5.0mm	
NSR		RAPID		5.0mm	
OSF		RAPID		5.0mm	
OSR		RAPID		5.0mm	
Spare					

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seatsHeight adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- · Cloth seat trim
- · Cruise control
- Rear wiper
- Electric door mirrors Front armrest
- · Rear electric windows
- ABS
- Side airbags
- · Alloy wheels

- Navigation system
- Steering wheel mounted controls Radio/CD
- Opening panoramic glass roof Front electric windows
- · Rear headrests
- Drivers airbag
- Central locking
- PAS
- Air conditioning
 Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- · Remote central locking

Photos

























Condition Check



Damage Photos



1: Bonnet Dented With Paint Damage



2: Bumper Front Dented With Paint Damage



3: Wheel osf Scratched Over 50mm




4: Door osf Dented With Paint Damage



5: Door osr Dented Between 10mm + 30mm



6: Wheel osr Scratched Over 50mm



7: Qtr Panel osr Dented Between 10mm + 30mm



8: Bumper Rear Scratched Over 100mm Thru Paint



9: Tailgate Scratched Over 25mm Thru Paint



10: Wheel nsr Scratched Over 50mm



11: Qtr Panel nsr Dented Between 10mm + 30mm



12: Door nsr Scratched Over 25mm Thru Paint



13: Door nsf Scratched Over 25mm Thru Paint




14: Wheel nsf Scratched Over 50mm



15: Wing nsf Scratched Over 25mm Thru Paint



16: A Post ns Chipped 1 To 5



17: Wing osf Dented Over 30mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	ОК
Windows	OK	Steering	OK
Sat nav	OK		