



VEHICLE INSPECTION REPORT

HK64FLR

Ford Focus 1.0 EcoBoost Titanium Navigator 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	17/12/2014	VIN	WF0KXXGCBKEB71295	CAP Average	£1,150.00
Year	2014	Body Style	Hatchback	CAP Below	£725.00
Mileage	114,361 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	29/08/2025	Gears	5
Colour	SILVER	CAP Clean	£1,575.00	Doors	5


£100 ADDITIONAL FEE.

Tyres		
NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Cloth seat trim
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Traction control
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image



3: Boot Lid
Scratched
Over 25mm Not Thru Paint


4: Qtr Panel nsr
Dented
With Paint Damage



5: Wheel nsr
Scratched
Over 50mm

6: Door nsr
Chipped
1 To 5

No Image



7: Door nsr
Scratched
Over 25mm Not Thru Paint

8: Door nsf
Scratched
UpTo 25mm Thru Paint

No Image

No Image

9: Door nsf
Scratched
Over 25mm Not Thru Paint

10: Wing nsf
Scratched
Over 25mm Not Thru Paint



11: Wheel nsf
Scratched
Over 50mm

12: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



13: Bumper Front
Scratched
Over 25mm Not Thru Paint

14: Bonnet
Chipped
1 To 5



15: Wing osf
Chipped
1 To 5



16: Wheel osf
Scratched
Up To 50mm



17: Door osf
Dented
Over 30mm



18: Door osr
Chipped
1 To 5



19: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



20: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK