



VEHICLE INSPECTION REPORT

EJ65HCO

Volvo XC60 D5 [220] SE Lux Nav 5dr AWD Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	18/12/2015	Keys	2	CAP Clean	£5,675.00
Year	2015	Service history	Yes	CAP Average	£4,950.00
Mileage	145,212 Miles Warranted	Service documents	Service Book	CAP Below	£4,225.00
Fuel Type	Diesel	Number of stamps	11	Gearbox	AUTOMATIC
Colour	BLUE	Last service date	11/12/2024	Gears	6
VIN	YV1DZ97C6G2851118	Last service miles	143,267		
Body Style	Estate	MOT Due	12/09/2025		

£100 ADDITIONAL FEE.

Last service 11/12/2024 at 143,267 miles- 11 services (7 main dealer)

Service history is book and printout

Tyres

NSF	BRIDGESTONE	3.0mm
NSR	PIRELLI	2.0mm
OSF	BRIDGESTONE	2.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Leather seat trim
- Cruise control
- Rear parking sensor
- Radio/CD
- Climate control
- Front head restraints
- Metallic Paint
- ESP
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint




4: Wing osf
Chipped
1 To 5

No Image

5: Wing osf
Scratched
Over 25mm Not Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osr
Chipped
1 To 5

8: Door osr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel osr
Chipped
Multiple Chips



10: Wheel osr
Scratched
Over 50mm




11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Dented
Over 30mm



13: Qtr Panel nsr
Dented
Between 10mm + 30mm




14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Wheel nsr
Scratched
Over 50mm



16: Door nsr
Dented
Between 10mm + 30mm



17: Door nsr
Scratched
Over 25mm Not Thru Paint



18: Wing nsf
Chipped
1 To 5



19: Door nsf
Rusted
Over 5mm



20: Wheel nsf
Scratched
Over 50mm



21: Roof
Rusted
Over 5mm

22: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK