



VEHICLE INSPECTION REPORT

LR05UFP

Land Rover Discovery 2.7 Td V6 HSE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/05/2005	Keys	1	CAP Clean	£1,950.00
Year	2005	Service history	Yes	CAP Average	£1,550.00
Mileage	114,105 Miles Warranted	Service documents	Service Book	CAP Below	£1,150.00
Fuel Type	Diesel	Number of stamps	14	Gearbox	AUTOMATIC
Colour	GREY	Last service date	05/08/2024	Gears	6
VIN	SALLAAA135A341139	Last service miles	109,574		
Body Style	Estate	MOT Due	16/11/2025		

LAST SERVICE 5/8/24 @ 109574 MILES (14 MILES 7 MAIN DEALER) BOOK AND PRINT Sunroof not working tapped on outside see photos

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Curtain airbags
- Rear airbags
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Full size spare wheel
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel nsf
Scratched
Over 50mm



2: Bonnet
Chipped
1 To 5



3: Door nsf
Chipped
Edge Chip



4: Door nsr
Dented
Between 10mm + 30mm



5: Wheel nsr
Scratched
Over 50mm



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel osr
Dented
Between 10mm + 30mm



8: Wheel osr
Scratched
Over 50mm



9: Door osr
Dented
Over 30mm



10: Door osf
Dented
With Paint Damage



11: Wheel osf
Scratched
Over 50mm



12: Roof
Chipped
Over 5mm



13: Fascia Panel
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		