



VEHICLE INSPECTION REPORT

B3EPE

Alfa Romeo Giulietta 1.4 TB MultiAir Veloce 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	30/09/2010	Keys	1	CAP Clean	£1,050.00
Year	2010	Service history	Yes	CAP Average	£660.00
Mileage	134,088 Miles Warranted	Service documents	Printout	CAP Below	£275.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	MANUAL
Colour	BLACK	Last service date	11/10/2024	Gears	6
VIN	ZAR94000007025378	Last service miles	134,088	Doors	5
Body Style	Hatchback	MOT Due	15/04/2026		

£80 ADDITIONAL FEE.

Last service 11/10/2024 at 134,088 miles- 1 service

No V5

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	ROADSTONE	4.0mm
Spare		

Features


- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Partial leather seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- ABS
- Central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Qtr Panel nsr
Poor Previous Repair
Poor Paint




4: Door nsr
Poor Previous Repair
Poor Paint



5: Wheel nsr
Scratched
Over 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Wing nsf
Dented
With Paint Damage



9: Wheel nsf
Scratched
Over 50mm




10: Bonnet
Chipped
1 To 5




11: Wing osf
Dented
Over 30mm



12: Wheel osf
Scratched
Over 50mm



13: Door osf
Chipped
1 To 5



14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Door osr
Dented
Over 2 UpTo 10mm



16: Qtr Panel osr
Dented
With Paint Damage



17: Wheel osr
Scratched
Over 50mm



18: Other
N/A
N/A



19: Bumper Front
Cracked
UpTo 25mm



20: A Post ns
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK