



VEHICLE INSPECTION REPORT

DV55WSK

Mercedes-Benz CLK CLK220 CDI AVANTGARDE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/12/2005	VIN	WDB2093082F186122	CAP Clean	£960.00
Year	2005	Body Style	Coupe	CAP Average	£580.00
Mileage	104,561 Miles Warranted	Keys	1	CAP Below	£325.00
Fuel Type	Diesel	Service history	None	Gearbox	AUTOMATIC
Colour	GREY	MOT Due	06/12/2025	Gears	6

£80 ADDITIONAL FEE.

No service history Gearbox fault and bulbs out on dash

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	ROADSTONE	Damaged
OSR	BUDGET	2.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front armrest
- Rear armrest
- ABS
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- Isofix child seat anchor points
- Partial leather seat trim
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Passenger airbag
- Alloy wheels
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Other
N/A
N/A

No Image



3: Tyre osf
Damaged
Replace

4: Bonnet
Poor Previous Repair
Poor Paint



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Poor Previous Repair
Paint Flake



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Bumper Rear Moulding
Broken
Replace



13: Boot Lid
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Rusted
Over 5mm



15: Wheel osr
Scratched
Over 50mm



16: Door osf
Dented
Over 30mm



17: Wing osf
Dented
With Paint Damage



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK