

# **VEHICLE INSPECTION REPORT**

**GJ62NYT** 

# Volkswagen Passat 2.0 TDI Bluemotion Tech SE 5dr DSG

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		5 gg S
		V5	TBC		
Details					
Reg. date	18/09/2012	VIN	WVWZZZ3CZDE032309	CAP Average	£850.00
Year	2012	Body Style	Estate	CAP Below	£475.00
Mileage	211,671 Miles Warranted	Keys	1	Gearbox	SEMI AUTO
		MOT Due	22/01/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£1,250.00		
Colour	BLUE				

#### £80 ADDITIONAL FEE. Engine knocking

Tyres	
-------	--

NSF	BUDGET	4.0mm	
NSR	CONTINENTAL	5.0mm	
OSF	BUDGET	4.0mm	
OSR	BUDGET	4.0mm	
Spare			_

### **Features**

- Cruise control
  Radio/CD
  Air conditioning
  Front head restraints
  Metallic Paint

- Drivers airbagSide airbagsAlloy wheels

- Body coloured bumpers Folding rear seats Height adjustable drivers seat
- 3x3 point rear seat belts Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrestRear electric windows
- ABS
- Passenger airbagRemote central locking
- Steering wheel mounted controls
- Front fog lights
  Front electric windows
  Rear headrests
  Curtain airbags

- Rear airbags
- Cloth seat trim

### **Photos**























# **Condition Check**



# **Damage Photos**



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched Over 100mm Thru Paint



3: Bumper Front Moulding Missing Replace



4: Wheel nsf Scratched Over 50mm



5: Wing nsf Dented With Paint Damage



6: Door nsf Dented With Paint Damage



7: Door nsr Scratched Over 25mm Thru Paint



8: Wheel nsr Scratched Over 50mm



9: Qtr Panel nsr Scratched Over 25mm Thru Paint



10: Bumper Rear Dented With Paint Damage



11: Tailgate Dented Over 30mm



12: Fuel Flap Missing Replace



13: Qtr Panel osr Scratched Over 25mm Thru Paint



14: Wheel osr Scratched Over 50mm



15: Door osr Chipped Over 5mm



16: Door osf Dented Over 30mm



17: Wheel osf Scratched Over 50mm



18: Wing osf Chipped 1 To 5



19: Fascia Panel Broken Replace

## Interior

**Carpet Condition Upholstery Condition** Average **Seat Condition** Odour Average

Average No

## **Vehicle Inspection Report**

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK