



# VEHICLE INSPECTION REPORT

**KS57LSN**

## Vauxhall Corsa 1.4i 16V Club 5dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	07/02/2008	Keys	1	CAP Clean	£220.00
Year	2008	Service history	Yes	CAP Average	£200.00
Mileage	146,402 Miles Warranted	Service documents	Electronic / Online	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	MANUAL
Colour	BLUE	Last service date	24/04/2025	Gears	5
VIN	W0L0SDL6884214318	Last service miles	142,551	Doors	5
Body Style	Hatchback	MOT Due	06/05/2026		

£30 ADDITIONAL FEE.

Last service 24/04/2025 at 142,551 miles- service confirmed by Ashdene Garage

### Tyres

NSF	BUDGET	3.0mm
NSR	AUTOGREEN	2.0mm
OSF	AUTOGREEN	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Dented  
With Paint Damage



2: Boot Lid  
Dented  
With Paint Damage






3: Qtr Panel nsr  
Dented  
With Paint Damage



4: Roof  
Poor Previous Repair  
Paint Flake



5: Door nsr  
Dented  
2 Or Less UpTo 10mm



6: Door nsr  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Rusted  
Over 5mm



8: Wing nsf  
Chipped  
1 To 5

No Image



10: Bonnet  
Dented  
With Paint Damage




11: Bumper Front  
Scratched  
Over 100mm Thru Paint



12: Other  
N/A  
N/A



13: Wing osf  
Chipped  
1 To 5




14: Screen Front  
Chipped  
UpTo 10mm





15: Door osf  
Chipped  
1 To 5



16: Door osf  
Scratched  
Over 25mm Not Thru Paint



17: Sill os  
Rusted  
Over 5mm



18: Qtr Panel osr  
Rusted  
UpTo 5mm



19: D Post os  
Poor Previous Repair  
Paint Flake



20: Door osr  
Poor Previous Repair  
Poor Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK