



# VEHICLE INSPECTION REPORT

**LG66UMY**

## Ford Mondeo 1.5 TDCi ECONetic Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	TBC



### Details

Reg. date	04/10/2016	VIN	WF0FXXWPCFGD69080	CAP Average	£5,300.00
Year	2016	Body Style	Estate	CAP Below	£4,475.00
Mileage	55,233 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	02/09/2025	Gears	6
Colour	BLUE	CAP Clean	£6,100.00		

### Tyres

NSF	HANKOOK	4.0mm
NSR	HANKOOK	4.0mm
OSF	AVON	3.0mm
OSR	HANKOOK	4.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Cloth seat trim
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- ESP
- Traction control
- Alloy wheels
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint






3: Wheel nsf  
Scratched  
Up To 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Chipped  
Multiple Chips



8: Door nsr  
Poor Previous Repair  
Poor Paint



9: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint




10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



14: Qtr Panel osr  
Dented  
With Paint Damage





15: Wheel osf  
Scratched  
Over 50mm



16: Door osf  
Dented  
With Paint Damage



17: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



18: Wing osf  
Chipped  
1 To 5



19: Wheel osf  
Scratched  
Up To 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK