



VEHICLE INSPECTION REPORT

GF22PZL

Alfa Romeo Stelvio 2.0 Turbo 280 Veloce 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	17/05/2022	VIN	ZARPAHJN0N7D44813	CAP Average	£20,800.00
Year	2022	Body Style	Estate	CAP Below	£19,400.00
Mileage	43,247 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Petrol	MOT Due	16/05/2026	Gears	8
Colour	BLACK	CAP Clean	£22,200.00		

£100 ADDITIONAL FEE. Front camera fault

Tyres		
NSF	NEXEN	5.0mm
NSR	GT RADIAL	5.0mm
OSF	NEXEN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Drivers airbag
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- ESP
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Bumper Front Moulding
Broken
Replace



4: Wheel nsf
Scratched
Up To 50mm




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
2 Or Less UpTo 10mm



7: Door nsr
Chipped
1 To 5




8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm




10: Qtr Panel nsr
Chipped
1 To 5




11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Chipped
Multiple Chips



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
1 To 5



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		