

VEHICLE INSPECTION REPORT

LF19ALM

Ford Mondeo 1.5 EcoBoost 165 Titanium Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	TBC

nama
GRADE
3

Details

Reg. date	26/07/2019	VIN	WF0EXXWPCEKY58085	CAP Average	£4,775.00
Year	2019	Body Style	Hatchback	CAP Below	£4,075.00
Mileage	91,990 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	Expired	Gears	6
Colour	GREY	CAP Clean	£5,500.00	Doors	5

Tyres


NSF	UNIROYAL	5.0mm
NSR	BUDGET	5.0mm
OSF	UNIROYAL	5.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Dented
Over 30mm



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
2 Or Less UpTo 10mm



7: Door nsr
Chipped
1 To 5

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Chipped
1 To 5



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




14: Wheel osr
Scratched
Over 50mm



15: Door osr
Dented
2 Or Less UpTo 10mm



16: Door osf
Chipped
1 To 5



17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK