



# VEHICLE INSPECTION REPORT

**LC13JBZ**

## Vauxhall Corsa 1.0 ecoFLEX S 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	29/06/2013	Keys	2	CAP Clean	£1,150.00
Year	2013	Service history	Yes	CAP Average	£740.00
Mileage	58,054 Miles Warranted	Service documents	Service Book	CAP Below	£350.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	BLUE	Last service date	24/09/2024	Gears	5
VIN	W0L0SDL08D6081608	Last service miles	56,491	Doors	3
Body Style	Hatchback	MOT Due	28/09/2025		

£80 ADDITIONAL FEE.

Last service 24/09/2024 at 56,491 miles- 8 services Rough idle

### Tyres


NSF	NEXEN	3.0mm
NSR	GOODYEAR	3.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	3.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front head restraints
- ABS
- Central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Drivers airbag
- Remote central locking
- Radio/CD
- Climate control
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim
- Body coloured bumpers
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5




2: Bonnet  
Scratched  
Over 25mm Not Thru Paint






3: Bumper Front  
Poor Previous Repair  
Poor Paint




4: Wing nsf  
Dented  
Over 2 UpTo 10mm



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsf  
Dented  
Over 2 UpTo 10mm



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Bumper Rear  
Poor Previous Repair  
Poor Paint

No Image


10: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



11: Qtr Panel osr  
Chipped  
1 To 5

No Image


12: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



13: Door osf  
Chipped  
1 To 5

No Image

14: Door osf  
Scratched  
Over 25mm Not Thru Paint



15: Wing osf  
Dented  
Over 2 UpTo 10mm

16: Wing osf  
Scratched  
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK