



VEHICLE INSPECTION REPORT

CY17EYO

Citroen Grand C4 Picasso 1.6 BlueHDi Flair 5dr EAT6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	04/07/2017	VIN	VF73ABHZTHJ713353	CAP Average	£4,650.00
Year	2017	Body Style	MPV	CAP Below	£3,950.00
Mileage	105,896 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	27/09/2025	Gears	6
Colour	BLUE	CAP Clean	£5,350.00		

£80 ADDITIONAL FEE. Sun roof fault doesn't close


Tyres


NSF	GOODYEAR	3.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	3.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Partial leather seat trim
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Solid Paint
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips

No Image



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
1 To 5



8: Door nsr
Chipped
1 To 5



9: Door nsr
Dented
Between 10mm + 30mm




10: Wheel nsr
Scratched
Over 50mm




11: Qtr Panel nsr
Poor Previous Repair
Poor Paint



12: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%



13: Boot Lid
Scratched
Over 25mm Not Thru Paint




14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




15: Wheel osr
Scratched
Over 50mm



16: Door osr
Chipped
1 To 5



17: Door osr
Scratched
Over 25mm Not Thru Paint




18: Door osf
Dented
Over 2 UpTo 10mm



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm

22: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		