



VEHICLE INSPECTION REPORT

GU12FKH

Ford Fiesta 1.4 TDCi [70] Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/03/2012	Keys	2	CAP Clean	£1,150.00
Year	2012	Service history	Yes	CAP Average	£750.00
Mileage	104,912 Miles Warranted	Service documents	Service Book	CAP Below	£370.00
Fuel Type	Diesel	Number of stamps	3	Gearbox	MANUAL
Colour	BLUE	Last service date	24/04/2020	Gears	5
VIN	WF0JXXGAJJCR61880	Last service miles	54,200	Doors	5
Body Style	Hatchback	MOT Due	28/08/2025		

£80 ADDITIONAL FEE.

LAST SERVICE 24/4/20 @ 54200 MILES (3 SERVICES 2 MAIN DEALER) BOOK Eml on and transmission warning light on dash

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- ESP
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Rear parking sensor
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage



3: Wing osf
Dented
With Paint Damage



4: Wheel osf
Scratched
Over 50mm



5: Door osf
Dented
With Paint Damage



6: Door osf
Poor Previous Repair
Poor Paint



7: Qtr Panel osr
Dented
With Paint Damage



8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Bumper Rear Moulding
Broken
Replace



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Up To 50mm



13: Door nsr
Dented
With Paint Damage



14: Door nsf
Chipped
Multiple Chips



15: Wing nsf
Dented
With Paint Damage

16: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK