

VEHICLE INSPECTION REPORT

BT61MVM

Vauxhall Corsa 1.4i 16V [100] SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	31/12/2011	VIN	W0L0SDL68C4072043	CAP Average	£200.00
Year	2011	Body Style	Hatchback	CAP Below	£200.00
Mileage	121,337 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	14/08/2026	Gears	5
Colour	GREY	CAP Clean	£490.00	Doors	5


Tyres

NSF	NEXEN	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Curtain airbags
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Drivers airbag
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Partial leather seat trim
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Torn
UpTo 3mm



2: Bonnet
Rusted
UpTo 5mm



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Chipped
1 To 5

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Bumper Rear
Poor Previous Repair
Poor Paint



13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Chipped
1 To 5



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Poor Previous Repair
Poor Paint



19: Wing osf
Dented
With Paint Damage



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK