



VEHICLE INSPECTION REPORT

WF13OWB

Volvo V60 D3 [136] SE Lux 5dr Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/05/2013	Keys	2	CAP Clean	£4,425.00
Year	2013	Service history	Yes	CAP Average	£3,825.00
Mileage	75,958 Miles Warranted	Service documents	Service Book	CAP Below	£3,225.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	AUTOMATIC
Colour	SILVER	Last service date	25/07/2024	Gears	6
VIN	YV1FW31A0D1137913	Last service miles	72,788		
Body Style	Estate	MOT Due	Expired		

£80 ADDITIONAL FEE.

Last service 25/07/2024 at 72,788 miles- 9 services (6 main dealer)

Cambelt replaced 10/12/24

Tyres

NSF	PIRELLI	6.0mm
NSR	FALKEN	Damaged
OSF	PIRELLI	6.0mm
OSR	BRIDGESTONE	7.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Air conditioning
- Front electric windows
- Rear headrests
- Curtain airbags
- Rear airbags
- Leather seat trim
- PAS
- Radio/CD
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Front TowEye Cvr
Missing
Replace




3: Headlamp Washer os
Missing
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Tyre nsr
Damaged
Replace



7: Wing nsf
Scratched
UpTo 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Dented
With Paint Damage



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Chipped
Edge Chip



15: Sill os
Scratched
Over 25mm Thru Paint



16: Door osf
Chipped
Over 5mm



17: Wing osf
Dented
With Paint Damage



18: Wheel osf
Scratched
Over 50mm



19: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK