



VEHICLE INSPECTION REPORT

LN63HTP

Jaguar F-Type 3.0 Supercharged V6 S 2dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2013	Keys	2	CAP Clean	£17,000.00
Year	2013	Service history	Yes	CAP Average	£15,650.00
Mileage	60,355 Miles Warranted	Service documents	Printout	CAP Below	£14,250.00
Fuel Type	Petrol	Number of stamps	11	Gearbox	AUTOMATIC
Colour	GREY	Last service date	31/08/2023	Gears	8
VIN	SAJAC65B7E8K01915	Last service miles	58,020		
Body Style	Convertible	MOT Due	10/08/2026		

£65 ADDITIONAL FEE.

Last service 31/08/2023 at 58,020 miles- 11 services (9 main dealer) Engine tapping when warm. Knocking while turning vehicle off

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Climate control
- Front electric windows
- Metallic Paint
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- ABS
- Traction control
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Drivers airbag
- Central locking
- Navigation system
- Audio remote control
- Air conditioning
- Front armrest
- Sports seats
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Chipped
1 To 5




4: Qtr Panel osr
Dented
Between 10mm + 30mm



5: Door osf
Chipped
1 To 5



6: Door osf
Scratched
Over 25mm Not Thru Paint



7: Wing osf
Scratched
Over 25mm Not Thru Paint



8: Bonnet
Chipped
1 To 5




9: Bumper Front
Poor Previous Repair
Poor Paint




10: Wing nsf
Chipped
1 To 5



11: Door nsf
Dented
2 Or Less UpTo 10mm



12: Door nsf
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



14: Wheel nsr
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		