



VEHICLE INSPECTION REPORT

EK71ZVX

Peugeot 208 1.2 PureTech 100 Allure Premium 5dr EAT8

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/10/2021	Keys	2	CAP Clean	£10,450.00
Year	2021	Service history	Yes	CAP Average	£9,400.00
Mileage	43,005 Miles Warranted	Service documents	Printout	CAP Below	£8,325.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	AUTOMATIC
Colour	WHITE	Last service date	13/11/2023	Gears	8
VIN	VR3UPHNKSMT091269	Last service miles	29,543	Doors	5
Body Style	Hatchback	MOT Due	06/08/2026		

£65 ADDITIONAL FEE.

Last service 13/11/2023 at 29,543 miles- 2 main dealer services Intermittent limp mode

Tyres


NSF	TRIANGLE	4.0mm
NSR	BUDGET	4.0mm
OSF	TRIANGLE	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Holed
UpTo 3mm



2: Carpets Front
Torn
Over 10mm



3: Carpets Front
Torn
Over 10mm



4: Bonnet
Chipped
1 To 5



5: Bumper Front
Chipped
Multiple Chips



6: Bumper Front
Scratched
Over 25mm Not Thru Paint



7: Bumper Front Grill
Broken
Replace



8: Wheel nsf
Scratched
Over 50mm

No Image



9: Wing nsf
Scratched
Over 25mm Not Thru Paint

10: Door nsf
Dented
Over 2 UpTo 10mm



11: Door nsr
Dented
2 Or Less UpTo 10mm



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Dented
With Paint Damage



14: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image



15: Bumper Rear
Scratched
Over 25mm Not Thru Paint

16: Boot Lid
Scratched
UpTo 25mm Thru Paint



17: Qtr Panel osr
Chipped
1 To 5



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Dented
2 Or Less UpTo 10mm



20: Door osf
Chipped
1 To 5

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Wing osf
Dented
Between 10mm + 30mm



23: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Poor
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK