



# VEHICLE INSPECTION REPORT

**GX15YRD**

## Ford Focus 1.5 EcoBoost Zetec S 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	31/03/2015	Keys	2	CAP Clean	£3,125.00
Year	2015	Service history	Yes	CAP Average	£2,625.00
Mileage	96,621 Miles Warranted	Service documents	Service Book	CAP Below	£2,150.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	WHITE	Last service date	10/02/2025	Gears	6
VIN	WF05XXGCC5ER16836	Last service miles	91,328	Doors	5
Body Style	Hatchback	MOT Due	30/03/2026		

Last service 10/02/2025 at 91,328 miles- 6 services (2 main dealer) Rattle while revving  
Abs and traction control light on

### Tyres


NSF	GOODYEAR	5.0mm
NSR	FARROAD	4.0mm
OSF	GOODYEAR	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- ESP
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Tyre osf  
Damaged  
Replace



2: Bonnet  
Chipped  
1 To 5



3: Bumper Front  
Chipped  
Multiple Chips

No Image

4: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



5: Wing nsf  
Chipped  
1 To 5

No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Wheel nsf  
Scratched  
Over 50mm



8: Door nsf  
Dented  
Over 2 UpTo 10mm



No Image

9: Door nsf  
Scratched  
Over 25mm Not Thru Paint



10: Door nsr  
Chipped  
1 To 5

No Image

11: Door nsr  
Scratched  
Over 25mm Not Thru Paint



12: Wheel nsr  
Scratched  
Over 50mm



14: Bumper Rear  
Dented  
With Paint Damage



13: Qtr Panel nsr  
Dented  
With Paint Damage



15: Boot Lid  
Chipped  
1 To 5



16: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



17: Qtr Panel osr  
Chipped  
1 To 5



18: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



19: Wheel osr  
Scratched  
Over 50mm



20: Door osr  
Chipped  
1 To 5

No Image



21: Door osr  
Scratched  
Over 25mm Not Thru Paint

22: Door osf  
Chipped  
1 To 5



23: Wing osf  
Chipped  
1 To 5



24: Wheel osf  
Scratched  
Over 50mm



25: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK