



VEHICLE INSPECTION REPORT

VK68FPG

Vauxhall Astra 1.6 CDTi 16V 136 SRi Nav 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2018	Keys	1	CAP Clean	£3,200.00
Year	2018	Service history	Yes	CAP Average	£2,725.00
Mileage	104,825 Miles Warranted	Service documents	Printout	CAP Below	£2,250.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	AUTOMATIC
Colour	GREY	Last service date	18/05/2025	Gears	6
VIN	W0VBF6EG4KG310524	Last service miles	102,332	Doors	5
Body Style	Hatchback	MOT Due	25/11/2025		

Last service 18/05/2025 at 102,332 miles- 9 services Engine tapping

Tyres



NSF	GOODYEAR	6.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Navigation system
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Chipped
Multiple Chips



3: Wheel osf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door osf
Dented
Between 10mm + 30mm



6: Door osr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Dented
With Paint Damage



12: Door osr
Chipped
1 To 5




13: Door osf
Scratched
Over 25mm Thru Paint



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5



16: Roof
Chipped
Edge Chip



17: Sill os
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK