



# VEHICLE INSPECTION REPORT

**GF73EBK**

## Volkswagen Polo 1.0 TSI Life 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/09/2023	Keys	2	CAP Average	£13,950.00
Year	2023	Service history	Yes	CAP Below	£12,800.00
Mileage	28,338 Miles Warranted	Service documents	Printout	Gearbox	SEMI AUTO
Fuel Type	Petrol	Number of stamps	2	Gears	7
Colour	GREY	Last service date	08/05/2025	Doors	5
VIN	WVVZZZAWZPU109325	Last service miles	18,906		
Body Style	Hatchback	CAP Clean	£15,100.00		

£65 ADDITIONAL FEE. Last service 08/05/2025 at 18906 miles (2 main dealer services).

### Tyres

NSF	GOODYEAR	3.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	3.0mm
OSR	GOODYEAR	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wheel nsf  
Scratched  
Up To 50mm

No Image

5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsf  
Chipped  
1 To 5



7: Door nsr  
Chipped  
1 To 5



8: Bumper Rear  
Chipped  
Multiple Chips

No Image

9: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

No Image

10: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



11: Wheel osr  
Scratched  
Up To 50mm



12: Door osr  
Chipped  
1 To 5

No Image

13: Door osr  
Scratched  
Over 25mm Not Thru Paint

No Image

14: Door osf  
Scratched  
Over 25mm Not Thru Paint



15: Door osf  
Chipped  
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK