

VEHICLE INSPECTION REPORT

EX20SXR

Vauxhall Insignia 1.6 Turbo D ecoTec Tech Line Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	TBC



Details

Reg. date	24/07/2020	VIN	W0VZT6ELXL1025402	CAP Below	£3,275.00
Year	2020	Body Style	Hatchback	Gearbox	MANUAL
Mileage	90,027 Miles Warranted	MOT Due	29/07/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£4,425.00	Doors	5
Colour	BLUE	CAP Average	£3,850.00		


Tyres

NSF	KUMHO	4.0mm
NSR	KUMHO	4.0mm
OSF	KUMHO	5.0mm
OSR	KUMHO	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- PAS
- Audio remote control
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Broken
Replace



4: Bumper Front Grill
Broken
Replace



5: Wing nsf
Dented
With Paint Damage



6: Wheel nsf
Scratched
Over 50mm




7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Dented
With Paint Damage



9: Door nsr
Dented
With Paint Damage



10: Sill ns
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Cracked
Over 25mm




14: Other
N/A
N/A



15: Qtr Panel osr
Dented
With Paint Damage



16: Boot Lid
Dented
Between 10mm + 30mm



17: Boot Lid
Chipped
Multiple Chips



18: Wheel osr
Scratched
Over 50mm



19: Door osf
Dented
With Paint Damage



20: Roof
Dented
Between 10mm + 30mm



21: C Post os
Dented
2 Or Less UpTo 10mm



22: C Post ns
Dented
Between 10mm + 30mm



23: Door osr
Dented
With Paint Damage



24: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



25: Wing osf
Dented
With Paint Damage



26: Wheel osf
Scratched
Over 50mm



27: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK