



VEHICLE INSPECTION REPORT

LB65LCG

Ford Focus 1.5 TDCi 120 Titanium 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|----------------|
| Serious Damage? | No | VAT | VAT Qualifying |
| | | V5 | TBC |



Details

| | | | | | |
|-----------|---------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 11/01/2016 | VIN | WF06XXGCC6FP84550 | CAP Average | £2,950.00 |
| Year | 2016 | Body Style | Estate | CAP Below | £2,425.00 |
| Mileage | 93,642 Miles Warranted | Keys | 2 | Gearbox | MANUAL |
| Fuel Type | Diesel | MOT Due | 24/11/2025 | Gears | 6 |
| Colour | RED | CAP Clean | £3,450.00 | | |


Tyres

| | | |
|-------|------------|-------|
| NSF | FALKEN | 5.0mm |
| NSR | BFGOODRICH | 4.0mm |
| OSF | KORMORAN | 3.0mm |
| OSR | FALKEN | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Solid Paint
- ESP
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Steering Wheel
Damaged
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Tailgate
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Dented
Over 2 UpTo 10mm



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Dented
Over 30mm



15: Door osf
 Scratched
 Over 25mm Thru Paint



16: Wheel osf
 Scratched
 Over 50mm



17: Wing osf
 Chipped
 1 To 5



18: Screen Front
 Chipped
 UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

| | | | |
|----------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |