



# VEHICLE INSPECTION REPORT

**HR19LFB**

## Ford Mondeo 1.5 EcoBoost 165 Titanium Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	12/08/2019	VIN	WF0FXXWPCFKS07320	CAP Average	£4,700.00
Year	2019	Body Style	Estate	CAP Below	£3,975.00
Mileage	103,583 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	11/08/2026	Gears	6
Colour	SILVER	CAP Clean	£5,425.00		

### Engine tapping

### Tyres

NSF	LAUFENN	5.0mm
NSR	FALKEN	Illegal
OSF	SUNNY	5.0mm
OSR	FALKEN	Illegal
Spare		

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front head restraints
- Metallic Paint
- ESP
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Chipped  
Multiple Chips





3: Wheel nsf  
Scratched  
Over 50mm



4: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



5: Door nsf  
Dented  
Between 10mm + 30mm



6: Door nsr  
Chipped  
Edge Chip



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint





9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Tailgate  
Scratched  
Over 25mm Thru Paint



11: Roof  
Dented  
Between 10mm + 30mm



12: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Door osr  
Chipped  
Edge Chip



15: Door osf  
Chipped  
Edge Chip



16: Wheel osf  
Scratched  
Over 50mm



17: Wing osf  
Scratched  
UpTo 25mm Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK