



VEHICLE INSPECTION REPORT

HN09VUG

Renault Megane 1.6 16V 110 Dynamique 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/07/2009	Keys	2	CAP Clean	£750.00
Year	2009	Service history	Yes	CAP Average	£350.00
Mileage	103,795 Miles Warranted	Service documents	Service Book	CAP Below	£225.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	RED	Last service date	16/09/2022	Gears	6
VIN	VF1BZ0V0641523166	Last service miles	85,153	Doors	5
Body Style	Hatchback	MOT Due	07/09/2025		

£65.00 ADDITIONAL FEE Last service 16/09/2022 @ 85153 miles (9 SERVICES) Possible exhaust leak


Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Service indicator
- Radio/CD
- Air conditioning
- Front head restraints
- Solid Paint
- Passenger airbag
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Central locking
- PAS
- Trip computer
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Remote central locking
- Rear wiper
- Audio remote control
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Colour



3: Wing osf
Chipped
1 To 5



4: Wheel osf
Scratched
Over 50mm



5: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



6: Door osf
Chipped
Multiple Chips



7: Door osr
Chipped
Multiple Chips



8: Qtr Panel osr
Chipped
1 To 5

No Image



10: Wheel osr
Scratched
Over 50mm



11: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%



12: Boot Lid
Scratched
Over 25mm Thru Paint



13: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



14: Wheel nsr
Scratched
Over 50mm



15: Door nsr
Scratched
Over 25mm Not Thru Paint



16: Door nsr
Scratched
Over 25mm Not Thru Paint



17: Wing nsf
Poor Previous Repair
Poor Paint



18: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK