



# VEHICLE INSPECTION REPORT

**GY17AMO**

## Kia Sportage 1.7 CRDi ISG 3 5dr DCT Auto [Panoramic Roof]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/03/2017	Body Style	Estate	MOT Due	27/10/2025
Year	2017	Service history	Yes	CAP Clean	£6,450.00
Mileage	99,092 Miles Warranted	Service documents	Service Book	CAP Average	£5,625.00
Fuel Type	Diesel	Number of stamps	8	CAP Below	£4,800.00
Colour	BLACK	Last service date	01/11/2024	Gearbox	SEMI AUTO
VIN	U5YPH815VHL220616	Last service miles	93,867	Gears	7

£65 ADDITIONAL FEE.

Last Service - 01.11.2024 at 93867 miles (8 services) Abs, traction control light on and high beam assist system.  
Tmps light on

### Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Leather seat trim
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Poor Previous Repair  
Poor Paint






3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Dented  
Over 2 UpTo 10mm



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Dented  
With Paint Damage





9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Scratched  
Over 100mm Thru Paint



11: Boot Lid  
Scratched  
Over 25mm Thru Paint



12: Qtr Panel osr  
Chipped  
1 To 5



13: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



14: Wheel osr  
Scratched  
Over 50mm





15: Door osr  
Dented  
With Paint Damage



16: Door osf  
Scratched  
Over 25mm Thru Paint



17: Wing osf  
Dented  
Over 2 UpTo 10mm



18: Wing osf  
Scratched  
Over 25mm Not Thru Paint



19: Wheel osf  
Scratched  
Over 50mm



20: Bumper Front Moulding  
Broken  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		