



VEHICLE INSPECTION REPORT

PX12ZWN

Mini Hatchback 1.6 Cooper 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/06/2012	Keys	2	CAP Clean	£1,700.00
Year	2012	Service history	Yes	CAP Average	£1,300.00
Mileage	114,026 Miles Warranted	Service documents	Service Book	CAP Below	£925.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	MANUAL
Colour	RED	Last service date	09/10/2024	Gears	6
VIN	WMWSU320X0T109833	Last service miles	110,962	Doors	3
Body Style	Hatchback	MOT Due	13/08/2025		

Last Service: 09/10/2024 at 110962 miles. (9 services (4 main dealer)) Slight suspension knock

Tyres


NSF	JINYU TIRES	3.0mm
NSR	RAPID	4.0mm
OSF	LAUFENN	4.0mm
OSR	BUDGET	Worn
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- PAS
- Body coloured bumpers
- Rear headrests
- ESP
- Central locking
- Rear wiper
- Electric door mirrors
- Solid Paint
- Passenger airbag
- Remote central locking
- Telephone
- Air conditioning
- ABS
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image




3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing osf
Chipped
1 To 5



5: Wheel osf
Scratched
Over 50mm

6: Door osf
Chipped
Multiple Chips



7: Qtr Panel osr
Dented
With Paint Damage

8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
Poor Previous Repair
Paint Flake




10: Boot Lid
Chipped
1 To 5




11: Qtr Panel nsr
Dented
Over 30mm



12: Wheel nsr
Scratched
Over 50mm



13: Door nsf
Dented
Over 2 UpTo 10mm



14: Door nsf
Scratched
UpTo 25mm Not Thru Paint




15: Wing nsf
Chipped
1 To 5



16: Wheel nsf
Scratched
Over 50mm



17: Tyre osr
Worn
Replace



18: Tyre osr
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK