



VEHICLE INSPECTION REPORT

PY10FDZ

BMW X1 xDrive 20d SE 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	28/06/2010	Body Style	Estate	Last service miles	82,728
Year	2010	Keys	1	MOT Due	05/07/2026
Mileage	120,527 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Electronic / Online	Gears	6
Colour	BLACK	Number of stamps	4		
VIN	WBAVP32050VK50222	Last service date	08/06/2018		

£65 ADDITIONAL FEE.

Last confirmed service 08/06/2018 at 82,728 miles- 4 services confirmed by Lloyds BMW, Carlisle Code 897 on dash

Boot only opens with key

Smoking

Loosing power

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Heated front seat
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Corroded
Light



4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Chipped
Multiple Chips




8: Door nsr
Poor Previous Repair
Poor Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Lamp osr
Broken
Replace



14: Qtr Panel osr
Chipped
1 To 5

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Wheel osr
Scratched
Over 50mm



17: Door osr
Poor Previous Repair
Poor Paint



18: Roof
Dented
Between 10mm + 30mm



19: Door osf
Chipped
1 To 5

No Image

20: Door osf
Scratched
Over 25mm Not Thru Paint



21: Wing osf
Dented
With Paint Damage



22: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



23: Wheel osf
Scratched
Up To 50mm



24: Boot Lid
Rusted
UpTo 5mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK