



VEHICLE INSPECTION REPORT

HW71MUB

Land Rover Range Rover Velar 2.0 P400e S 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/12/2021	Keys	2	CAP Clean	£26,500.00
Year	2021	Service history	Yes	CAP Average	£25,200.00
Mileage	28,857 Miles Warranted	Service documents	Printout	CAP Below	£23,800.00
Fuel Type	Hybrid Electric	Number of stamps	1	Gearbox	AUTOMATIC
Colour	BLUE	Last service date	30/01/2024	Gears	8
VIN	SALYA2AY1MA327516	Last service miles	19,958		
Body Style	Estate	MOT Due	22/12/2025		

£65 ADDITIONAL FEE

Last service 30/01/2024 at 19,958 miles- 1 service Type 2 and 3 pin charging cables

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Curtain airbags
- Rear airbags
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Dented
Between 10mm + 30mm



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



11: Door osr
Scratched
UpTo 25mm Thru Paint



12: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Door osf
Scratched
UpTo 25mm Thru Paint



14: Wing osf
Scratched
Over 25mm Thru Paint

No Image

No Image

15: Door osr
Scratched
Over 25mm Not Thru Paint

16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		