

### **VEHICLE INSPECTION REPORT**

**MJ67XLF** 

### Vauxhall Astra 1.0T ecoTEC SRi 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Present		
Details					
Reg. date	20/11/2017	Keys	2	CAP Clean	£3,325.00
Year	2017	Service history	Yes	CAP Average	£2,825.00
Mileage	92,438 Miles	Service documents	Service Book	CAP Below	£2,325.00
	Warranted	Number of stamps	7	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	15/01/2025	Gears	5
Colour	WHITE	Last service miles	86,097	Doors	5
VIN	W0VBF6EA5JG027110	MOT Due	05/10/2025		
Body Style	Hatchback				

#### £65 ADDITIONAL FEE

Last service 15/01/2025 at 86,097 miles- 7 services (4 main dealer)

т	v	r	e	s
•	y	•	·	J

NSF	RAPID	4.0mm	
NSR	BUDGET	3.0mm	
OSF	RAPID	4.0mm	
OSR	BUDGET	4.0mm	
Spare			

#### **Features**

- · Bluetooth connection
- Rear wiper
- · Body coloured bumpers
- Front armrest
- · Rear electric windows
- ABS
- Traction control
- · Alloy wheels


- Cruise control
- Steering wheel mounted controls Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Air conditioning
- Front head restraints
- Metallic Paint
- · Isofix child seat anchor points
- · Remote central locking
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Cloth seat trim

#### **Photos**






















### **Condition Check**



### **Damage Photos**



1: Bonnet Chipped 1 To 5



2: Bumper Front Chipped Multiple Chips

# No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Over 50mm

# No Image

5: Wing nsf Scratched Over 25mm Not Thru Paint



6: Door nsf Dented Over 2 UpTo 10mm

## No Image

7: Door nsf Scratched Over 25mm Not Thru Paint




8: Door nsr Dented Between 10mm + 30mm

## No Image

## No Image

9: Door nsr Scratched Over 25mm Not Thru Paint





11: Wheel nsr Scratched Over 50mm



12: Bumper Rear Scratched 25 to 100mm Thru Paint

## No Image

## No Image

13: Bumper RearScratchedOver 25mm Not Thru Paint

14: Boot Lid Scratched Over 25mm Not Thru Paint



15: Qtr Panel osr Scratched Over 25mm Thru Paint



16: Wheel osr Scratched Over 50mm



17: Door osr Scratched UpTo 25mm Thru Paint

# No Image

18: Door osr Scratched Over 25mm Not Thru Paint



19: Door osf Chipped 1 To 5

# No Image

20: Door osf Scratched Over 25mm Not Thru Paint



21: Wing osf Chipped 1 To 5



22: Wheel osf Scratched Over 50mm

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

#### Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
		, , , , , , , , , , , , , , , , , , ,	
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK