

VEHICLE INSPECTION REPORT

GJ14YJP

Audi A3 1.4 TFSI S Line 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	Present		
Details					
Reg. date	29/03/2014	Keys	2	CAP Clean	£4,875.00
Year	2014	Service history	Yes	CAP Average	£4,250.00
Mileage	114,293 Miles Warranted	Service documents	Printout	CAP Below	£3,625.00
		Number of stamps	5	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	30/12/2024	Gears	6
Colour	WHITE	Last service miles	104,414	Doors	5
VIN	WAUZZZ8V2EA147890	MOT Due	05/01/2026		
Body Style	Hatchback		33, 3 = 3=3		

£100 ADDITIONAL FEE

Lasts service 30/12/2024 at 104,414 miles- 5 services (3 main dealer)

Tyres

NSF	APOLLO	5.0mm	
NSR	APOLLO	5.0mm	
OSF	APOLLO	5.0mm	
OSR	APOLLO	5.0mm	
Spare			

Features

- · Bluetooth connection
- Rear wiper
- · Electric door mirrors
- Folding rear seats
- · Height adjustable drivers seat
- 3x3 point rear seat beltsESP
- Central locking
- Cruise control
- Steering wheel mounted controls Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Remote central locking
- PAS
- Space saver spare wheel
- Front electric windows
- · Rear headrests
- · Curtain airbags
- Passenger airbag
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Mica Paint
- Drivers airbag
- Side airbags
- Alloy wheels

Photos












Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched Over 100mm Thru Paint



3: Wheel nsf Scratched Over 50mm



4: Door Mirror Assy nsf Scratched (Painted) UpTo 25mm Thru Paint



5: Door nsf Dented Over 30mm



6: Door nsr Dented Over 30mm



7: Wheel nsr Scratched Over 50mm



8: Qtr Panel nsr Dented With Paint Damage



9: Bumper RearScratched25 to 100mm Thru Paint



10: Wheel osr Scratched Over 50mm



11: Qtr Panel osr Dented 2 Or Less UpTo 10mm



12: Door osf Chipped Edge Chip



13: Door osr Dented 2 Or Less UpTo 10mm



14: Wheel osf Scratched Over 50mm



15: Tailgate Dented With Paint Damage

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting		Gearbox Static Gear Selection (engine running)	
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
		, , , , , , , , , , , , , , , , , , ,	
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK