



# VEHICLE INSPECTION REPORT

**GY67TSV**

## Vauxhall Astra 1.4T 16V 150 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	29/11/2017	Keys	2	CAP Clean	£4,175.00
Year	2017	Service history	Yes	CAP Average	£3,550.00
Mileage	81,973 Miles Warranted	Service documents	Service Book	CAP Below	£2,925.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	GREY	Last service date	31/07/2024	Gears	6
VIN	W0VBD6EC0JG026521	Last service miles	65,717	Doors	5
Body Style	Hatchback	MOT Due	26/08/2026		

£100 ADDITIONAL FEE  
Last service 31/07/2024 at 65,717 miles- 7 services (6 main dealer)


Tyres		
NSF	NEXEN	5.0mm
NSR	LAUFENN	5.0mm
OSF	TOYO	5.0mm
OSR	NEXEN	5.0mm
Spare		

## Features


- Bluetooth connection
  - Rear parking sensor
  - Body coloured bumpers
  - Front electric windows
  - Rear headrests
  - Drivers airbag
  - Side airbags
  - Alloy wheels
- Cruise control
  - Rear wiper
  - Electric door mirrors
  - Front head restraints
  - Metallic Paint
  - ESP
  - Central locking
- Heated front seat
  - Steering wheel mounted controls
  - Air conditioning
  - Height adjustable drivers seat
  - 3x3 point rear seat belts
  - Isofix child seat anchor points
  - Remote central locking
- PAS
  - Digital radio
  - Folding rear seats
  - Rear electric windows
  - ABS
  - Passenger airbag
  - Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wheel osf  
Scratched  
Over 50mm



4: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Thru Paint



5: Door osf  
Scratched  
Over 25mm Thru Paint



6: Door osr  
Dented  
With Paint Damage



7: Wheel osr  
Scratched  
Over 50mm



8: Rear TowEye Cvr  
Missing  
Replace





9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Qtr Panel nsr  
Dented  
Over 30mm



11: Door nsr  
Dented  
Over 30% Of Panel



12: Door nsf  
Dented  
With Paint Damage



13: Wheel nsf  
Scratched  
Over 50mm



14: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK